




Ssangyong Actyon Sport
2006 -
Ref. 1618





Ssangyong Actyon Sport


2006 -

Ref. 1618

Samenstelling - Composition - Zusammenstellung

	2 x	DIN9021-M12 (ø37x13x3mm)	A
	3 x	DIN934 - M12 - 8.8	A-C
	4 x	DIN933 - M12x35 - 8.8	B-C-D
	2 x	DIN931 - M12x120 - 8.8	A
	6 x	DIN128-A12-FSt	A-B-C-D

GDW Ref. ①	2 x	
GDW Ref. ②	1 x	



Bouten – Boulons – bolts – Bolzen: Kwaliteit 8.8	DIN 912 – DIN 931 – DIN 933 – DIN 7991
M6 ≈ 10,8Nm of 1,1kgm	M8 ≈ 25,5Nm of 2,60kgm
M12 ≈ 88,3Nm of 9,0kgm	M14 ≈ 137Nm of 14,0kgm
M16 ≈ 211,0Nm of 21,5kgm	

Bouten – Boulons – bolts – Bolzen: Kwaliteit 10.9	DIN 912 – DIN 931 – DIN 933 – DIN 7991
M6 ≈ 13,7Nm of 1,4kgm	M8 ≈ 35,3Nm of 3,6kgm
M12 ≈ 122,6Nm of 12,5kgm	M14 ≈ 194Nm of 19,8kgm
M16 ≈ 299,2Nm of 30,5kgm	

Bouten – Boulons – bolts – Bolzen: Kwaliteit 12.9	DIN 912 – DIN 931 – DIN 933 – DIN 7991
M6 ≈ 18Nm of 1,8kgm	M8 ≈ 43Nm of 4,4kgm
M12 ≈ 150Nm of 15,3kgm	M14 ≈ 240Nm of 24,5kgm
M16 ≈ 370Nm of 37,7kgm	